

# Work Identified for Building Block Survey Summary

**Building Name:** 2021 - Haylands Primary School

**0 - External Works** **Gross Internal Area:** 0 m<sup>2</sup>  
**Age of Block:** **Gross External Area:** 0 m<sup>2</sup>  
**Survey Date** **Survey Status** **Surveyor** **Mechanical Surveyor** **Electrical Surveyor**  
 01/02/2005 Complete Chuck Eccleston

**Element Total by Priority**

Element	Grade	1	2	3	Total 1 - 3	4
01 - Roofs		0	0	0	0	0
02 - Floors and stairs		0	0	0	0	0
03 - Ceilings		0	0	0	0	0
04 - External walls windows and doors		0	0	0	0	0
05 - Internal walls and doors		0	0	0	0	0
06 - Sanitary services		0	0	0	0	0
07 - Mechanical Services		0	0	0	0	0
08 - Electrical Services		0	0	0	0	0
09 - Redecorations		0	1,389	505	1,894	0
10 - Fixed furniture and fittings		0	0	0	0	0
		<b>0</b>	<b>1,389</b>	<b>505</b>	<b>1,894</b>	<b>0</b>

**1 - MAIN SCHOOL BUILDING** **Gross Internal Area:** 1566 m<sup>2</sup>  
**Age of Block:** BT07 - Post 1996 **Gross External Area:** 0 m<sup>2</sup>  
**Survey Date** **Survey Status** **Surveyor** **Mechanical Surveyor** **Electrical Surveyor**  
 01/02/2005 Complete Chuck Eccleston

**Element Total by Priority**

Element	Grade	1	2	3	Total 1 - 3	4
01 - Roofs	B	2,678	0	0	2,678	0
02 - Floors and stairs	B	0	0	0	0	0
03 - Ceilings	B	0	207	150	357	0
04 - External walls windows and doors	B	0	74	396	471	0
05 - Internal walls and doors	B	0	0	304	304	0
06 - Sanitary services	B	0	0	0	0	0
07 - Mechanical Services	B	0	520	0	520	0
08 - Electrical Services	B	0	0	223	223	0
09 - Redecorations	B	6,393	5,461	24,527	36,382	0
10 - Fixed furniture and fittings	B	0	0	0	0	0
		<b>9,071</b>	<b>6,262</b>	<b>25,600</b>	<b>40,933</b>	<b>0</b>

End of Report